





F2

3x




E2

2x




D2

2x




B2

2x




Z

2x




U

1x




V

1x




W

1x




X

1x




C2

2x




A2

2x




P

1x




Q

3x




R

1x




S

1x




Y

2x




K

8x




L

6x




M

4x



N

2x




T

2x




F

100x



G

2x




H

24x




I

2x




O

8x




A

112x




B

32x




C

68x



D



18x








E

18x












60 min



1




2





3/8








3



4




4/8




5/8









7



8



This diagram shows the exploded view of the assembly. It includes a base plate (R), a screw (J), a washer (Z), a nut (A), a pin (B), a bracket (C), and a spring (D). The components are arranged to show their relative positions and how they fit together.



10

